

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter section corner common to Sections 26 and 35, T1S, R7W, WM, Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which:

5" Vinemaple bears S56W 20 lks.; now missing, vine maple clump in vicinity.

8" Hem. bears N25W 19 lks.; now 12" uproot, roots and root hole in place, part of scribes 1/4 visible, rest burnt out.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S26 S35 1955 RE 2311," 33" inches in ground, in mound of stone, and from which a;

30" Fir sna bears N20W 66.2 ft.; scribed 1/4 S26 BT RE2311.


5" Fir bears S7 1/2 E 29.2 ft.; scribed 1/4 S35 BT.

Oregon State Board of Forestry metal location poster on 5" Fir BT.

Set 3" x 3" x 60" white Cedar post 1 1/2 ft. N. of pipe.

Dated April 11, 1955.

Restored by Richard A. Morris under my direction.



Present and witnessed by Lloyd Geraths
Forrest Logan
Claude Weikel