

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

— EAST SIDE SEC. 24 —

One-quarter section corner common to Section 24, T. 1S.,
R. 8W., W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

10" Fir bears N79°W 28 lks.; now 24" stub, 6' high,
scribes $\frac{1}{4}$ S BT visible.

RESTORED

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" Bronze cap
marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S24 1955
RE 2311," 33 inches in ground, in mound of stone,
and from which a:

66" Fir snag bears S22°W 89.5 ft.; scribed $\frac{1}{4}$ S24 BT
RE 2311.

Oregon State Board of Forestry metal location poster on
66" Fir snag BT.

Set 4" x 4" x 72" white Cedar post 1 ft. E of pipe.

Dated April 11, 1955.

Restored by Richard A. Morris under my direction.
Richard A. Morris, Engr. Aide



Present and witnessed by Claude Weikel
Forrest Logan