

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Closing corner common to Sections 18 and 19, T. 3N.,
R. 6W., W.M., Tillamook County, Oregon.

ORIGINAL

Stone 24"x20"x16", now missing, point located in slide
area, from which a:

- 6" Fir bears N70°30'E 5 lks.; now 66" stump, scribes
BT visible on lower face, upper face burnt out.
- 36" Hemlock bears S22°E 97 lks.; now missing, point falls
in slide area.
- 24" Hemlock bears S14°30'W 16 lks.; now missing, point
falls in slide area.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY T3N R7W S13, T3N R6W S18
cc S19 1955 RE 2311,"

60" Fir stump bears S82°E 16.5 ft.; scribed T3N R6W S19
CC BT RE 2311.

72" Fir stump bears N12°E 35.1 ft.; scribed T3N R6W S18
CC BT.

Set 4"x4"x72" white painted Cedar post 3' NE of pipe
Oregon State Board of Forestry metal location poster on 72"
Fir stump BT.

Also poster on 4"x4"x72" white painted Cedar post approx.
1250' N. on N. edge of logging road.

Dated September 20, 1955

Restored by Richard A. Morris under my direction.
Richard A. Morris, C.E. I



Present and witnessed by Robert Sturm
Forrest Logan
Lloyd Geraths