

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 3, 4, 9 and 10, T. 3N., R. 8W., W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 20" x 9" x 4" (found downhill out of place, with 5 notches on one face and 3 on adjacent face) from which a:

- 5" Hemlock bears N.53°E. 80 lks.; now missing
- 24" Hemlock bears S.40°E. 24 lks.; now missing, just roots remaining in place.
- 72" Fir bears S.7°W. 20 lks.; now 80" snag, scribes 8W visible, rest unexposed.
- 16" Hemlock bears N.33°W. 50 lks.; now 2' high root stub, scribes & face burnt off.

RESTORED

Var. 21-1/2° E.

Set original stone in place with 5 notches on S. & 3 on E. faces, 10 inches in ground, in mound of stone, and from which a:



- 7" Fir bears N.42°W. 19.6 ft.; scribed T3N R8W S4 BT RS359.
- 10" Fir bears N.51°E. 66.8 ft.; scribed T3N R8W S3 BT.
- 15" Cedar bears S.17°E. 63.7 ft.; scribed T3N R8W S10 BT.

Oregon State Board of Forestry metal location poster on 10" Fir BT.

Set 4 x 4 x 66" white painted Cedar post 1 Ft. S.E. of original stone.

Dated May 14, 1956

Restored by Richard Morris under my direction.
Richard Morris, Transitman



Present and witnessed by Robert Sturm