

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 24 and 25  
T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 80" Fir bears S72°E 44 lks.; now 73" stump, faces unexposed.
- 40" Fir bears N7°30'E 53½ lks.; now 48" stump, scribes  
BT exposed, upper face cut off when logged.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap  
marked "OREGON STATE BOARD OF FORESTRY ¼ S24 S25  
1957 RS 359," 34 inches in ground, and from which a:


- 11" Fir bears S17°E 12.2 ft.; scribed ¼ S25 BT RS 359.
- 7" Fir bears N17°E 28.5 ft.; scribed ¼ S24 BT.

Oregon State Board of Forestry metal location poster on  
11" Fir BT.

Set 4"x4"x60" white painted Cedar post 1.5' SE of pipe.

Dated February 21, 1957.

Restored by Richard Morris under my direction.  
Richard Morris, Transitman



Present and witnessed by Lloyd Geraths  
Robert Sturm