

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 25 and 36,
T3N, R6W, W.M., Tillamook County, Oregon

ORIGINAL

Post (missing) from which a:

24" Fir bears N83°W 54 lks.; now just roots and
root stub in place.

28" Hemlock bears S34½°E 46½ lks.; now 23" stub 15"
high, edges of old burnt out face visible.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY ¼ S25 S36 1957
RS 359," 34 inches in ground, and from which a:

9" Fir bears S83°W 38.2 ft.; scribed ¼ S36 BT.


10" Fir bears N27°E 22.4 ft.; scribed ¼ S25 BT RS 359.

Oregon State Board of Forestry metal location poster on
10" Fir BT.

Also poster on 11" Fir approximately 1050 feet E on
E edge of road.

Dated February 21, 1957.

Restored by Richard Morris under my direction.
Richard Morris, Transitman



Present and witnessed by Robert Sturm
Lloyd Geraths