

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

* Section corner common to Sections 9, 10, 15 and 16
T. 1S, R. 7W, W.M., Tillamook County, Oregon

ORIGINAL

Post (now missing) from which a:

- 36" Hemlock bears N76°W 127 lks.; now 46" snag, scribes visible on charred face.
- 35" Hemlock bears S88°W 172 lks.; now 36" snag, scribes T1S R7W remaining, rest of upper face burnt off, lower face unexposed.
- 10" Cedar bears S87°E 132 lks.; now missing, just root hole remaining in place.
- 10" Cedar bears N64°E 105 lks.; now missing.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R7W S9 S10 S16 S15 1957 RS401," 33 inches in ground, and from which a:

- 30" Cedar Snag bears N51°E 87.5 ft.; scribed T1S R7W S10 BT.
- 79" Fir snag bears N87°W 101.5 ft.; scribed T1S R7W S9 BT.
- 62" Fir stump bears S74°E 102.0 ft.; scribed T1S R7W S15 BT RS401.


Oregon State Board of Forestry metal location poster on 30" Cedar snag BT. Set 4" x 4" x 60" white painted Cedar post 1.0' SE of pipe.

Dated October 25, 1957

Restored by



Richard A. Morris



Present and witnessed by Robert Sturm
Harold Russell