

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 25 and 36 (East side)
T. 3N, R. 7W, W.M., Tillamook and Washington Counties,
Oregon.

ORIGINAL

Basalt stone 30" x 18" x 7" (now missing, point falls in slide area) from which a:

- 8" Hemlock bears N47°E 22 lks.; now missing.
- 18" Yew bears S82°E 51 lks.; now 15" snag, burnt out face with old axe marks visible, scribes reported destroyed by 1893 survey.
- 18" Yew bears S20°W 9 lks.; now 12" stub 1' high, slid down hill out of place, face and scribes burnt off.
- 24" Fir bears N66°W 39 lks.; now 30" snag, scribes BT visible, upper face burnt out.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R7W R6W S25 S31 S36 1957 RS401," 33 inches in ground, in mound of stone, and from which a:


- 5" Fir bears S63½°W 20.7 ft.; scribed T3N R7W S36 BT.
- 6" Fir bears N23°W 14.2 ft.; scribed T3N R7W S25 BT RS401.

Oregon State Board of Forestry metal location poster on 5" Fir S69°W 2.1 ft. Set 4" x 4" x 60" white painted Cedar post 1.3' SE of pipe.

Dated October 25, 1957



Richard A. Morris



Present and witnessed by Robert Sturm
Harold Russell