

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 25, 26, 35 and 36,
T. 2 N, R. 10 W, W.M., Tillamook County, Oregon

ORIGINAL

Post (now missing, found 1½" x 32" iron pipe out of place) from which a:

- 15" Hemlock bears S45E 12 lks.; now 35", scribes S36 visible on partly exposed face.
- 9" Hemlock bears N72E 18 lks.; now missing.
- 9" Hemlock bears N42W 19 lks.; now missing.

RESTORED

Var. 21½

Set above 1½" x 32" iron pipe in place and from which a:

- 23" Hemlock bears S14W 21.4 ft.; scribed T2N R10W S35 BT RS 401.
- 28" Hemlock bears N55½E 21.1 ft.; scribed T2N R10W S25 BT.
- 24" Hemlock bears N50½W 32.4 ft.; scribed T2N R10W S26 BT.
- Original 35" Hemlock bears S45E 7.9 ft.; scribed BT.


Oregon State Board of Forestry metal location poster on 23" Hemlock BT.
Set 4" x 4" x 60" white painted Cedar post 2.0' N.W. of pipe.

Dated January 24, 1958

Restored by



Richard A. Morris



Present and witnessed by Lloyd Geraths