

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 5, 6, 7 and 8,
T. 2N, R. 9W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone, 20" x 10" x 10" (found 10" x 6" x 9" stone with 5 notches on S. face, and 3/4" iron bolt with 1 1/4" square head on N.E. edge of stone) from which a:

- 14" Hemlock bears N36W 168 lks.; found possible tree bears N33W 111.6 Ft., no evidence of face or scribes.
- 12" Alder bears N69E 40 lks.; now missing.
- 6" Alder bears S42E 83 lks.; now missing.
- 42" Cedar bears S12W 16 lks.; now 74" snag, old rotted face visible, no scribes remaining.

RESTORED

Var. 21 1/2 E

Erected mound of stone around original corner stone from which a:

- 92" Spruce bears S37E 171.4 ft.; scribed T2N R9W S8 BT.
- 33" Hemlock bears N87E 117.6 ft.; scribed T2N R9W S5 BT.
- 41" Hemlock bears S86W 51.3 ft.; scribed T2N R9W S7 BT RS401.
- 48" Hemlock bears N33W 111.6 ft.; scribed T2N R9W S6 BT.


Oregon State Board of Forestry metal location poster on 48" Hemlock BT.
Set 4" x 4" white painted Cedar post on NE edge of corner stone.

Dated January 24, 1958

Restored by



Richard A. Morris



Present and witnessed by Robert Sturm
Harold Russell

Book I