

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Closing corner common to Sections 23 and 26 (West end), T. 2S, R. 9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 24" Hemlock bears S42E 3 lks.; now 32" uproot, roots and root hole in place, portion of scribes visible on partly exposed face.
- 6" Hemlock bears N30<sup>0</sup>/<sub>2</sub>E 24 lks.; now missing.

RESTORED

Var. 21<sup>1</sup>/<sub>2</sub>E

Set 1<sup>1</sup>/<sub>2</sub>" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R9W S27 S23 S26 CC 1958 RS401", 32 inches in ground, in mound of stone, and from which a:

- 26" Hemlock bears N84E 49.8 ft.; scribed T2S R9W S23 CC BT RS401.
- 9" Hemlock bears S21E 61.0 ft.; scribed T2S R9W S26 CC BT.


- Oregon State Board of Forestry metal location poster on 26" Hemlock BT.
- Set 4" x 4" x 72" white painted Cedar post 2.3' S.E. of pipe.

Dated June 23, 1958

Restored by



*Richard A. Morris*



Present and witnessed by Robert Sturm  
Harold Russell  
Lloyd Geraths

Book I

340

340