

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner for E. boundary Section 22,
T. 2S, R. 9W, W.M., Tillamook County, Oregon

ORIGINAL

Post (missing) from which a:

- 12" Hemlock bears N32E 33 lks.; now 31", face unexposed.
- 24" Hemlock bears S89W 51 lks.; now 40" snag, scribes 1/4 S BT visible.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S22 1958 RS401", 33 inches in ground, in small mound of stone, and from which a:


- 42" Cedar bears N25 1/2 W 68.8 ft.; scribed 1/4 S22 BT RS401.
- Original 12" Hemlock bears N32E 21.8 ft.; scribed BT on overgrowth.

Oregon State Board of Forestry metal location poster on original 12" Hemlock BT.


Set 4" x 4" x 72" white painted Cedar post 1.3' N.E. of pipe.

Dated June 23, 1958

Restored by



Richard A. Morris



Present and witnessed by Robert Sturm