

CHAINS

REESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY
(See official plat)

One Quarter corner common to Sections 19 and 30, T3S,
R9W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED

Var. 21 1/2 E

At intersection of line between Sec. Cor. 19-24-25-30 and Sec. Cor. 19-20-29-30 and line projected from 1/4 30 & 31 through Hayes center 1/4 Sec. 30, set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S19 S30 1958 RS401", 33 inches in ground, and from which a:

- 17" Fir bears N81 1/2 E 51.6 ft.; scribed 1/4 S19 BT RS401.
- 10" Fir bears S42 1/2 W 50.7 ft.; scribed 1/4 S30 BT.

Oregon State Board of Forestry metal location poster on 17" Fir BT.
Set 4" x 4" x 54" white painted Cedar post 2.2' N.E. of pipe.

Section corner common to Sections 19, 24, 25 and 30;
T3S, R. 9 & 10W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

RESTORED By Hayes 1887

(No evidence of bearing trees or corner monument found)

Brook 20 lks. Course E bears South 80 lks; ~~now~~ now in place.

REESTABLISHED

On line between 1/4 19 & 24 and 1/4 25 & 30, 80 lks. N of creek recorded in Hayes survey of 1887, set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3S R10W R9W S24 S19 S25 S30 1958 RS401", 26 inches in ground, in mound of stone, and from which a:

- 19" Hemlock bears S19E 135.5 ft.; scribed T3S R9W S30 BT.
- 11" Hemlock bears S20 1/2 W 108.8 ft.; scribed T3S R10W S25 BT.
- 22" Fir bears N52W 127.0 ft.; scribed T3S R10W S24 BT.
- 5" Spruce bears N69W 1.4 ft.; scribed RS401.


Oregon State Board of Forestry metal location poster on 5" Spruce BT.
Set 4" x 4" x 54" white painted Cedar post 3.7' N.E. of pipe.

Dated December 15, 1958

Reestablished by



Richard A. Morris



Present and witnessed by H. Russell
R. Schulson
R. Cop

Book I