

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 29 and 30,
T3N, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 6" Hemlock bears N38 $\frac{1}{2}$ E 45 lks.; now missing.
- 25" Hemlock bears S71W 13 lks.; now 28" rotted stub 15' high, scribes
1/4 S visible.

RESTORED

Var. 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S30 S29 1959 RS401", 34 inches in ground, in small
mound of stone, and from which a:


- 44" Fir stump bears S51W 5.0 ft.; scribed 1/4 S30 BT RS401.
- 33" Fir stump bears N11 $\frac{1}{2}$ E 40.5 ft.; scribed 1/4 S29 BT.

Oregon State Board of Forestry metal location poster on 38" Fir snag N9W
34.6

Set 4" x 4" x 48" white painted Cedar post 1.0 feet N.W. of pipe.

Dated August 4, 1959

Restored by Harold Russell under my direction
Harold Russell, Transitman



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401

Present and witnessed by D. Jones

Book I

368

368

368