

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 22 and 23,
T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

16" Spruce bears N43W 48 lks.; now missing.

48" Hemlock bears S41E 9 lks.; now 50" stump, scribes 1/4 S visible.

RESTORATION February 7, 1888 by County Surveyor's office

Set post (missing) from which a:

30" Hemlock bears S51W 49 lks.; now 31" stump, scribes 1/4 S visible.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON
STATE BOARD OF FORESTRY 1/4 S22 S23 1959 RS401," 33 inches in ground,
and from which a:


31" Hemlock bears N31 1/2 W 29.3 ft.; scribed 1/4 S22 BT RS401.

18" Hemlock bears N46E 37.1 ft.; scribed 1/4 S23 BT.


Oregon State Board of Forestry metal location poster on 18" Hemlock B.T.
Set 4" x 4" x 56" white painted Cedar post 1.0' N.E. of pipe.

Dated July 13, 1959

Restored by



Richard A. Morris



Present and witnessed by H. Russell
R. Cop
D. Ray