

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 13 and 18,
T1N, R9 and 10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 6" Hemlock bears N16W 45 lks.; now missing.
- 34" Hemlock bears S60E 22 lks.; now 30" stump, axe marks on bottom of old rotted out face visible.

Summit of ridge bears North 10 chains; now in place.
2 original line blazes North of corner point.

RESTORED

Var. 21½E


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S13 S18 1959 RS401", 34 inches in ground, in mound of stone, and from which a:

- 14" Fir bears S75E 35.5 ft.; scribed 1/4 S18 BT RS401.
- 12" Fir bears S28W 24.5 ft.; scribed 1/4 S13 BT.

Oregon State Board of Forestry metal location poster on 12" Fir B.T.
Set 4" x 4" x 56" white painted Cedar post 1.5 ft. N.W. of pipe.

Dated July 13, 1959

Restored by



Richard A. Morris
MAY 10, 1957

Richard A. Morris
401

Present and witnessed by H. Russell
R. Cop