

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 31 & 36,
T1N, R9 & 10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 48" Hemlock bears N80E 12 lks.; now 24" badly rotted uproot, roots in place, face and scribes rotted off.
- 88" Hemlock bears N55W 75 lks.; now 60" stub 8' high, face and scribes rotted off.
- 72" Spruce line tree bears South 150 lks.; now 48" uproot, roots and root hole in place.
- 50 lk. creek bears North 550 lks.; now in place.

RESTORED

Var. 21½E


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S36 S31 1959 RS401", 33 inches in ground, in mound of stone, and from which a:

- 15" Spruce bears N7W 47.3 ft.; scribed 1/4 S36 BT. RS401.
- 6" Spruce bears S44E 28.1 ft.; scribed 1/4 S31 BT.


Oregon State Board of Forestry metal location poster on 15" Spruce BT.
Set 4" x 4" x 56" white painted Cedar post 1.0' N.W. of pipe.

Dated April 14, 1959

Restored by



Richard A. Morris



Present and witnessed by H. Russell
R. Cop