

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 10, 11, 14 and 15, T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 30" Hemlock bears S45W 23 lks.; now 33", scribes S15 visible, rest unexposed.
- 20" Hemlock bears S20E 26 lks.; now 24" snag, scribes S14 visible, rest unexposed.
- 14" Spruce bears N36E 196 lks.; now missing.

RESTORED

Var. 21 $\frac{1}{2}$ E


Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R10W S10 S11 S15 S14 1959 RS401", 34 inches in ground, in mound of stone, and from which a:

- 40" Hemlock bears N41E 34.4 ft.; scribed T1N R10W S11 BT RS401.
- 10" Cedar bears N71W 33.7 ft.; scribed T1N R10W S10 BT.
- 12" Hemlock bears S74E 43.1 ft.; scribed T1N R10W S14 BT.


Oregon State Board of Forestry metal location poster on 40" Hemlock BT.
Set 4" x 4" x 56" white painted Cedar post 1.0 foot N.E. of pipe.

Dated August 4, 1959

Restored by Harold J. Russell under my direction.
Harold Russell, Eng. Tech. I



Richard A. Morris



Present and witnessed by D. Ray