

CHAINS

REESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 10 and 15, T3N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED

Var. 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S10 S15 1960 RS401", 33 inches in ground, and from which a:

26" Hemlock bears S24W 38.4 ft.; scribed 1/4 S15 BT.
18" Fir bears N6W 66.4 ft.; scribed 1/4 S10 BT RS401.

Oregon State Board of Forestry metal location poster on 3" Hemlock S16E 5.6'.
Set 4" x 4" x 72" white painted Fir post 1.0' S.E. of pipe.
Corner point falls 5 feet S. of creek.
Set 4" x 4" x 60" Cedar post S88°36'12"E 862.1 on W. bank of road.

One Quarter corner common to Sections 14 and 15, T3N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED

Var. 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S15 S14 1960 RS401", 33 inches in ground, and from which a:


14" Hemlock bears N6 $\frac{1}{2}$ W 3.6 ft.; scribed 1/4 S15 BT RS401.
10" Fir bears N30E 13.2 ft.; scribed 1/4 S14 BT.

Oregon State Board of Forestry metal location poster on 14" Hemlock BT.
Set 4" x 4" x 60" white painted Cedar post 1.0' S.W. of pipe.

Dated May 6, 1960

Reestablished by

Present and witnessed by R. Cop
E. Nylund



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401