

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 9, 10, 15 and 16, T3N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 10" Hemlock bears N28 $\frac{1}{2}$ E 60 lks.; now missing, position falls in old skid road.
- 20" Hemlock bears S30E 50 lks.; now rotted stub 3' high, face and scribes rotted away.
- 8" Hemlock bears S43W 90 lks.; now missing.
- 70" Cedar bears N36W 31 lks.; now 70" stump, back cast of scribe visible, face rotted away.

RESTORED

Var. 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R9W S9 S10 S16 S15 1960 RS401", 30 inches in ground, and from which a:

- 16" Hemlock bears S68W 17.7 ft.; scribed T3N R9W S16 BT.
- 18" Hemlock bears N60 $\frac{1}{2}$ W 56.0 ft.; scribed T3N R9W S9 BT.
- 26" Hemlock bears S83E 23.7 ft.; scribed T3N R9W S15 BT.
- 26" Hemlock bears N35E 51.0 ft.; scribed T3N R9W S10 BT RS401.

Oregon State Board of Forestry metal location poster on 14" Hemlock S41E 0.5 ft.

Set 4" x 4" x 60" white painted Fir post 1.0' N.E.

Dated May 6, 1960

Restored by



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401

Present and witnessed by R. Cop
E. Nylund