

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 1, 2, 11 and 12, T2S, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 20" Hemlock bears N40E 70 lks.; now 24" uproot, scribes BT visible, rest rotted away, now bears N70E 70 lks.
- 32" Hemlock bears N51W 63 lks.; now just rotten root stub remaining in place with 18" Hemlock growing out of remains.
- 16" Hemlock bears S52W 7 lks.; now 12" stub 2' high, scribes and face rotted away.
- 72" Spruce bears S83E 103 lks.; now 70" uproot, root hole in place, scribe BT visible, rest unexposed.

RESTORED

Var. 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R10W S2 S1 S11 S12 1960 RS401", 33 inches in ground, and from which a:

- 18" Hemlock bears N53W 41.0 ft.; scribed T2S R10W S2 BT.
- 28" Hemlock bears S73W 26.6 ft.; scribed T2S R10W S11 BT RS401.
- 19" Hemlock bears S60E 11.2 ft.; scribed T2S R10W S12 BT.
- 17" Hemlock bears N72E 12.6 ft.; scribed T2S R10W S1 BT.


Oregon State Board of Forestry metal location poster on 28" Hemlock BT.
Set 4" x 4" x 60" white painted Cedar post 1.5' S.E. of pipe.

Dated April 26, 1960

Restored by



Richard A. Morris



Present and witnessed by R. Cop
G. Nylund
M. Flippen