

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One quarter corner for Sections 11 and 14, T3N, R10W,
W.M., Tillamook County, Oregon.

ORIGINAL

40" Hemlock corner tree (now 56", with outline of face on north side,
and cruiser marks).

RESTORED

Var. 21 1/2 E

Rescribed corner tree, 1/4 S11 on North face, 1/4 S14 on South face from
which a:

7" Cedar bears N11W 65.7 ft.; scribed 1/4 S11 BT RS 401.

5" Hem. bears S72 1/2 E 21.3 ft.; scribed 1/4 S14 BT.


Oregon State Forestry Department metal location poster on 7" Cedar BT.

Dated April 16, 1963

Restored by



Richard A. Morris



Present and witnessed by B. Davis
H. Russell

1/4 Cor.
S. B. P. R. Y.
11-3.N.10