

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One Quarter corner common to Sections 17 and 20, T3S, R3W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing, found 3/4" x 48" iron pipe in place) from which a:

- 12" Fir bears S3W 18 lks.; now 42", scribes 1/4 visible, rest unexposed.
- 5" Barberry bears N58E 32 lks.; now missing.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S17 S20 1961 RS401", 34 inches in ground, over above 3/4" iron pipe, and from which a:


- 39" Fir bears N20E 93.1 ft.; scribed 1/4 S17 BT RS401.
- 42" Fir (Original) bears S3W 11.9 ft.; scribed BT on new face.

Oregon State Forestry Department metal location poster on original Fir BT.

Set 4" x 4" x 54" white painted Cedar post 1.0' N.E. of corner pipe.

Dated April 6, 1962

Restored by



*Richard A. Morris*  
MAY 10. 1957  
Richard A. Morris  
401

Present and witnessed by E. Nylund  
H. Russell  
A. Duncan

1/4 C.S.  
S. B. B. B.  
17-3-S.B.