

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One Quarter corner common to Sections 9 and 10, T6S, R9W,
W.M., Tillamook County, Oregon.

ORIGINAL

No evidence of original corner found.

RESTORATION by Unknown Party, notes recorded in County Surveyor's office
1887 - No evidence of restoration found.

RETRACEMENT by Morris Wygant, 1908

3 lk. Creek, course NE, bears North 225 lks.; in place.

Ridge top bears North 700 lks.; in place.

20" Fir line tree bears North 950 lks.; now 36" stp. uproot, out of
place, roots in place in cat road.

NOTE: Found possible original and retracement blazes on 24" dead Hemlock
bearing South 120.0 ft.

Found 23" Hemlock stp. bearing South 16.7 ft.; scribes BM 1008.2
visible.

RESTORED

Var. 20 $\frac{1}{2}$ " E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S9 S10 1962 RS559", 33 inches in ground, and from
which a:

6" Hemlock bears S39W 21.6 ft.; scribed 1/4 S9 BT.

4" Fir bears N76E 10.1 ft.; scribed 1/4 S10 BT.


30" Fir stp. bears S9E 19.2 ft.; scribed RS559.

Oregon State Forestry Department metal location poster on 4" Fir BT.

Set 4" x 4" x 72" white painted Cedar post 1.0' SE of corner pipe.

Dated August 6, 1962

Restored by



Present and witnessed by John Hollingsworth
Lance Hazelbaker
Curt Stone

1/4 cor
E. B. Driver
9-6 S. 9.