

June 28, 1953

The quarter corner common to Sections 24 and 25, T2N, R7W, W.M.; Tillamook County, Oregon.

Due to the fact that this quarter corner will unavoidably be destroyed by high lead logging, I was employed by the Forest Grove Lumber Company to reference it in such a manner that its location will not be lost.

From the corner restored by the Oregon State Board of Forestry dated November 17, 1954:

- A stone 20"x12"x9" in a mound of rock with a white painted post 3 feet to the SW;
- A scribed 24" double fir snag S27 $\frac{1}{2}$ W, 34.1 feet from corner;
- A scribed 17" fir stump N 56 E, 29.1 feet;

I placed an 8d nail in notch on root of the two following objects:

- A 30" fir snag bearing N 3 W, 127.8 feet and
- A 30" green fir tree bearing N 63 W, 154.2 feet.

Bearings by staff compass, needle with the declination set at 22 E.

REGISTERED
OREGON
LAND SURVEYOR

D. E. Bosworth

JAN. 1, 1943
D. E. Bosworth
82