

(9)

CHAINS

SURVEY FOR THE OREGON STATE BOARD OF FORESTRY

February 1, 1951

Var. 22° E.

Restoration of the $\frac{1}{4}$ corner to Sections 32 & 33, Township 2 North, Range 6 West, W.M., Tillamook County, Oregon.

The point for corner determined by the remains of the original bearing trees:

A fir snag, 26 inches in diam., bears S 41° 15' E, a distance of 23.1 feet (35 lks). Exposed the scribe marks: 4 S.

No evidence of $\frac{1}{4}$ corner stone or hemlock BT.

At the point for corner:


Set a $1\frac{1}{2}$ inch iron pipe, 3 feet long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped: $\frac{1}{4}$ S32 S33 1951 199.

from which:

A fir stump, 45 inches in diam., bears S 12° W, a distance of 59.8 feet, scribed: $\frac{1}{4}$ S32 199 BT.

Placed a metal location poster on the 26 inch fir snag BT, marked: Sec 33 T2N R6W $\frac{1}{4}$ cor 21.9 Ft. N 41° W.

Work done by Don Davis, Transitman; Richard Morris and Donald Newlen, Chaimen; Bill Kleeman and Adolf Berglund, Flagmen; under my direction.



Lyle E. Beyers
Forest Engineer

