

CHAINS

SURVEY FOR THE OREGON STATE BOARD OF FORESTRY

January 15, 1951

Restoration of the  $\frac{1}{4}$  corner to Sections 29 & 32, Township 2 North, Range 6 West, Tillamook County, Oregon.

Var.  $22^{\circ}$  E.

The point for corner determined from the remains of the original bearing trees:

A fir stump, 48 inches in diam., bears  $S 65^{\circ} W$ , a distance of 6.5 feet (10 lks.), scribe mark B exposed.

A hemlock stub, 24 inches in diam., bears  $N 54^{\circ} W$ , a distance of 21.1 feet (32 lks.), scribe marks  $\frac{1}{4}$  exposed.

At the point for corner:


Set a  $1\frac{1}{2}$  inch iron pipe, 3 feet long, with an Oregon State Board of Forestry bronze cap stamped:  $\frac{1}{4}$  S29 S32 1951 199.

From which:

A hemlock tree, 24 inches in diam., bears  $N 09^{\circ} 30' E$ , a distance of 48.5 feet, scribed:  $\frac{1}{4}$  S29 199 Br.

Placed a metal location poster on the 48 inch fir stump B1 and marked it: Sec 32 T2N R6W  $\frac{1}{4}$  cor. 5.5 ft.  $N 65^{\circ} E$ .

The above work done by Don Davis, Transitman; Richard Morris and Bill Kleeman, Chainmen; and John McWade, Flagman; under my direction.



Lyle E. Beyers  
Forest Engineer