

CHAINS

SURVEY FOR THE OREGON STATE BOARD OF FORESTRY

January 11, 1951

Restoration of the $\frac{1}{4}$ corner to Sections 17 & 20, Township 2 North, Range 6 West, W.M., Tillamook County, Oregon.

Var. 22° E.

The point for corner determined by the remains of the original bearing trees:

A fir snag, 24 inches in diam., bears $S 70^{\circ} W$, a distance of 25.1 feet (33 lks.), scribe marks: $\frac{1}{4}$ S B^r exposed.


A hemlock stump, 33 inches in diam., bears $N 79^{\circ} E$, a distance of 16.5 feet (25 lks.), scribe marks: $\frac{1}{4}$ S B exposed.

At the corner point:

Set a $1\frac{1}{2}$ inch iron pipe, 3 feet long, with an Oregon State Board of Forestry bronze cap stamped: $\frac{1}{4}$ S17 S20 1951 199.

Placed a metal location poster on a 30 inch hemlock stump and marked it: Sec 17 T2N R6W $\frac{1}{4}$ Cor. 17.5 ft. $N 43^{\circ} E$.

The above work done by Don Davis, Transitman; Richard Morris and Bill Kleeman, Chainmen; and John McWade, Flagman; under my direction.



Lyle E. Beyers
Forest Engineer