

5291 Stream 6 inches wide course South 65° East

5302.4 The corner to Sections 5, 6, 7, 8, bears North 13° 48' East, a distance of 59.4 feet. The corner determined by the squared point of the original hemlock stake found eighteen inches in the ground from which the following evidence of the original bearing trees were found:

The roots of a Yew which had fallen and burned to the point. No marks were visible. Bears South 40° West, a distance of 27.7 feet.

The stump hole and roots in ground of hemlock, bears North 71° West a distance of 17.8 feet.

The stump hole and roots in ground of a hemlock, bears South 55° East, a distance of 7.9 feet.

Adjustment of temporary stakes to true line position and establishment of corners and monuments.

Relative to the compass bearing of the random line the true line between Sections 5 and 8, bears North 89° 16' West, a distance of 5299.5 feet.

1372 Set a 4 X 4 inch cedar post on line between Sections 5 and 8 on the East side of a road with a metal location poster marked Sec. 5 & 8, T 1N, R 6W, Sec. Cor. 4, 5, 8, 9, 1372 feet East.

2649.7 Point of 1/4 corner to Sections 5 and 8. Adjustment from temp. stake 2651.2 North 24.1 feet East 12.6 feet.

Set a 1 1/2 inch iron pipe, 3 feet long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped 1/4 S 5 S 8 1950, 199.

from which:

A live fir 6 inches in diameter, bears North 74° 30' West, a distance of 79.5 feet scribed 1/4 S 5, 199

A live fir 6 inches in diameter, bears South 69° 30' East, a distance of 114.9 feet. Scribed 1/4 S 8

A metal location poster on a fir snag 30 inches in diameter, bears North 34° 30' West, a distance of 24.3 feet

Placed a mound of stones 2 feet in diameter 1 foot high around corner pipe.

Present:

Lyle E. Beyers
Don Davis
M. C. Bryant
Harry Myers

Lyle E. Beyers
Forest Engineer

(cont. from 59)