

CHAINS

RESTORED CORNER FOR THE OREGON STATE BOARD OF FORESTRY

November 15, 1951

One quarter corner between sections 3 & 4, Township 2 South, Range 7 West, W. M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

5" V. maple S27W 44 lks, now missing.

18" Hemlock S59 $\frac{1}{2}$ E 58 lks, now a 24" stub, badly burnt; scribe marks visible in 1951 since burnt out.

RESTORED CORNER & BEARING TREES

At the point for corner


Set a 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S4 S3 1951 142" $\frac{21}{32}$ ft. in ground. Raised a mound of rock around it, from which a:

36" Fir snag bears S54W 70.0 ft.; scribed $\frac{1}{4}$ S4 BT 142.

67" Fir stump bears S78 $\frac{1}{2}$ E 92.2 ft.; scribed $\frac{1}{4}$ S3 BT 142.


(Distances measured from center of bearing trees).

Nailed a metal location poster on the 67" Fir stump & marked it: Sec 3 T2S R7W 1/4 Cor 89.3 ft. N78W.



Restored by

Walter M. Robertson



Walter M. Robertson

Present & Witnessed by *Don Davis*
Don Davis Asst. Forest Engineer OSBF

Present & Witnessed by *Richard Morris*
Richard Morris Chairman OSBF

Present & Witnessed by *Leonard Koster*
Leonard Koster

Present & Witnessed by *Webb Howell*
Webb Howell