

(84)

CHAINS

RESTORED CORNER FOR THE OREGON STATE BOARD OF FORESTRY

November 13, 1951

The corner to sections 20, 21, 28, 29, Township 2 South, Range 7 West, W. M., Tillamook County, Oregon.

The point for corner determined by the remains of a 2" x 2" fir post (in place) which I set in 1947 S 64 W 25 lks from a 7" Barberry stub with both blazes evident; scribe marks burnt out (since destroyed). The remaining bearing trees destroyed by fire and logging.

At the point for the corner

Set a 1 1/2" x 36" galvanized iron pipe with 3" bronze cap stamped: "OREGON STATE BOARD OF FORESTRY T2S R7W S20 S21 S28 1951 142", 2 1/2 ft. in ground, from which a:


72" Fir stump bears S37E 109.1 ft.; scribed: T2S R7W S28 BT 142.

78" Fir stump bears N76°30' W 122.9 ft.; scribed: S20 BT 142.

65" Fir stump bears N 74° 30' E 84.6 ft.; scribed: T2S R7W S21 BT 142.

8" Alder tree bears S32W 125.0 ft.; bark scribed: S29 BT. (Distances measured from the center of bearing trees).

Nailed a metal location poster on the 72" fir stump BT and marked it: Sec 28 T2S R7W Sec cor 109.1 ft. N37W.



Restored by

Walter M. Robertson
 JAN. 1, 1945
 WALTER M. ROBERTSON
 142

Walter M. Robertson

Present & Witnessed by

Don Davis
 Don Davis Asst. Forest Engineer OSBF

Present & Witnessed by

Richard Morris
 Richard Morris Chairman OSBF