

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 22 and 23, T. 2 S., R. 7 W.,
W. M., Tillamook County, Oregon.

ORIGINAL

Stone, 16" x 16" x 4"; now missing, from which a:

12" Fir bears N17 $\frac{1}{2}$ W 130 lks; now a down 24" snag, scribe
marks not yet exposed.

12" Fir bears N12 $\frac{1}{2}$ E 137 lks; now a 12" stub 4 ft. high,
scribe marks 1 S exposed.

RESTORED CORNER AND BEARING TREES

Set a 16" x 16" x 4" stone marked $\frac{1}{4}$ on West face. Raised mound
of stone around it from which a:

28" Fir bears N21 $\frac{1}{2}$ W 105.1 ft.; scribed 1/4 S22 2311 BT.
Rock outcrop bears N84 3/4E 119.5 ft., the flat West face
of which is marked: BO (letters 4" high).

Placed an Oregon State Board of Forestry metal location poster
on the 28" Fir BT and marked it: Sec 22 T2S R7W 1/4 Cor
105.1 ft. S21 $\frac{1}{2}$ E.

Dated December 31, 1951.

This corner was restored by Arnold G. Gibson
Arnold G. Gibson Assistant Engineer
under my direction.



Present and witnessed by Don D. Davis
Don D. Davis Assistant Forest Engineer

Present and witnessed by Richard A. Morris
Richard A. Morris Compassman