

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 14, 15, 22 and 23, T. 2 S., R. 7 W., W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing from which a:

- 7" Hemlock bears N71 $\frac{1}{2}$ W 14 lks; now a 7" stub.
- 36" Hemlock bears S78 $\frac{1}{2}$ W 35 lks; now a 36" stub 8 ft. high, badly burnt.
- 40" Fir bears S15 $\frac{1}{2}$ E 28 lks; now a 44" stump, scribe marks S R 7 exposed.
- 5" Hemlock bears N15E 13 lks; now missing.

RESTORED CORNER AND BEARING TREES


Set a 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R7W S15 S14 S22 S23 1951 2311", 2 $\frac{1}{2}$ ft. in ground. Raised mound of stone around pipe from which a:

- 26" Fir snag bears N59E, 28.2 ft.; scribed T2S R7W S14 2311 BT.
- 28" Fir stump bears N35W 48.8 ft.; scribed T2S R7W S15 BT.
- 28" Fir snag bears S89 3/4W 43.7 ft.; scribed T2S R7W S22 BT.
- Rock ledge, the south face of which bears S80E 41 ft.

Placed an Oregon State Board of Forestry metal location poster on the 28" Fir snag BT, and marked it: Sec 14 T2S R7W Sec Cor 28.2 ft. S59 W.

Dated December 31, 1951.

This corner was restored by Arnold G. Gibson
 Arnold G. Gibson Assistant Engineer
 under my direction.



Present and witnessed by Don D. Davis
 Don D. Davis Assistant Forest Engineer

Present and witnessed by Richard A. Morris
 Richard A. Morris Compassman