

(96)

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Quarter corner to sections 21 and 28, T. 2 S., R. 7 W., W. M., Tillamook County, Oregon.

ORIGINAL

Post; now missing, from which a:

- 10" Hemlock bears S30W 21 lks; now 16" stub, scribe marks 1/4 BT exposed.
- 5" Vine Maple bears N32E 30 lks; now missing.

RESTORED CORNER AND BEARING TREES

Set a 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY S21 S28 1/4 S 1951 2311", 2 1/2 ft. in ground. Raised mound of stone around pipe from which a:

- 90" Fir stub, 8 ft. high and burnt out inside, bears S60E 37.5 ft; scribed 1/4 S28 2311 BT.
- 80" Fir stump bears N37E 101.5 ft; scribed 1/4 S21 BT.

Placed an Oregon State Board of Forestry metal location poster on 40" hemlock stub and marked it: Sec 21 T2S R7W 1/4 Cor 18 lks S75E.

Dated December 31, 1951.

This corner was restored by Arnold G. Gibson,
Arnold G. Gibson Assistant Engineer
under my direction.



Present and witnessed by Don D. Davis
Don D. Davis Assistant Forest Engineer