

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 1, 2, 11 and 12, T. 2 S., R. 7 W., W. M., Tillamook County, Oregon.

ORIGINAL

Post, now missing from which a:

30" Hemlock bears S18E 27 lks; now 40" stub 6 ft. high, scribe marks visible.

8" Hemlock bears N52 $\frac{1}{2}$ W 41 lks; now missing.

26" Fir bears S60 $\frac{1}{2}$ W 53 lks; now a 40" stub, 10 ft. high, burnt out face covered with 5 ft. of dirt and rotted out.

8" Hemlock bears N52 $\frac{1}{2}$ E 23 lks; now down and burnt.

RESTORED CORNER AND BEARING TREES

Set a 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R7W S2 S1 S11 S12 1951 2311", 2 $\frac{1}{2}$ " in ground. Raised mound of stone around pipe from which a:

48" Fir stump bears N70E 13.5 ft.; scribed T2S R7W S1 BT.

40" Hemlock stub bears S16E 17.8 ft.; rescribed T2S R7W S12 BT.

40" Fir stub bears S60 $\frac{1}{2}$ W 32.5 ft.; rescribed T2S R7W S11 2311 BT.

38" Hemlock stump bears N72W 18.5 ft.; scribed T2S R7W S2 BT.

Placed an Oregon State Board of Forestry metal location poster on 40" Hemlock stub BT and marked it: Sec 12 T2S R7W Sec Cor 27 lks N18 W.

Dated December 31, 1951.

This corner was restored by Arnold G. Gibson,
Arnold G. Gibson Assistant Engineer
under my direction.



Present and witnessed by Don D. Davis
Don D. Davis Assistant Forest Engineer

Present and witnessed by Richard A. Morris
Richard A. Morris Compassman