

(100)

CHAINS

RESTORATION FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 2 and 11, T. 2 S., R. 7 W., W.M. Tillamook County, Oregon.

ORIGINAL

Post, now missing from which a:

32" Hemlock bears N28E 18 lks; now a 33" snag, scribe marks 1/4 S exposed.

29" Hemlock bears S10W 57 lks; now missing.

RESTORED CORNER AND BEARING TREES

Set a 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R7W S2 S11 1951 2311" 2 1/2 ft. in ground. Raised mound of stone around pipe from which a:

40" Fir stump bears S79E 23.1 ft.; scribed 1/4 S11 BT.

48" Fir stump bears N73W 65.7 ft.; scribed 1/4 S2 2311 BT.

Placed an Oregon State Board of Forestry metal location poster on the 33" Hemlock snag BT and marked it: Sec 2 T2S R7W 1/4 Cor 11.9 ft. S28W.

Dated December 31, 1951.

This corner was restored by Arnold G. Gibson
Arnold G. Gibson Assistant Engineer
under my direction.



Present and witnessed by Don D. Davis
Don D. Davis Assistant Forest Engineer

Present and witnessed by Richard A. Morris
Richard A. Morris Compassman