

(103)

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 27 and 28, T2S R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Post; now missing, from which a:

36" Fir bears S52 3/4E 82 lks; now 44" snag, top face exposed and rotted.

30" Fir bears West 15 lks; now 34" snag, scribe marks BT exposed.

RESTORED CORNER AND BEARING TREES

Set a 1 1/2" x 36" galvanized iron pipe with 3" brass cap marked "OREGON STATE BOARD OF FORESTRY S28 S27 1/4S 1951 2311", 2 1/2 ft. in ground. Raised mound of stone around pipe from which a:


48" Fir stump bears S76 1/2W 18.5 ft.; scribed 1/4 S28 2311 BT.

88" Fir stump bears N88E 83.0 ft.; 1/4 S27 BT.

Placed an Oregon State Board of Forestry metal location poster on 88" fir snag BT and marked it: S28 T2S R7W 1/4 Cor. 15 lks. East.

Dated December 31, 1951.

This corner was restored by Arnold G. Gibson,  
Arnold G. Gibson Assistant Engineer  
under my direction.



Present and witnessed by Don D. Davis  
Don D. Davis Assistant Forest Engineer