

CHAINS

SURVEY FOR THE OREGON STATE BOARD OF FORESTRY

Reestablishment of the monument for the 1/4 section corner common to section 12, T. 1 N., R. 7 W., W. M., Tillamook County, Oregon.

The point for corner determined from 1/4 section corner common to section 7, T1N, R6W, a 1 1/2" galvanized iron pipe with 3" bronze cap stamped "OREGON STATE BOARD OF FORESTRY 1/4 S7 1949 199", from which a:

32" Hemlock stub bears S80W 13.9 ft; scribe marks BT exposed.

36" Hemlock stub bears S62E 23.1 ft; no evidence of marks found.

12" Fir stub bears S28E 24.3 ft; scribed 1/4 S7 199 BT.

At a point 91.7 ft. south of the 1/4 corner common to section 7 T1N R6W.



Set a 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S12 1949 199", 2 1/2 ft. in ground, from which a.

39" Fir snag bears S80W 25.5 ft; scribed 1/4 S12 199 BT.

Placed an Oregon State Board of Forestry metal location poster on 39" Fir snag and marked it: Sec 12 T1N R7W 1/4 Cor 24.8 ft. N80E.

Dated June 7, 1951.

This corner was reestablished by Don D. Davis
Don D. Davis Asst. Forest Engineer
under my direction.



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by Douglas Stafford Chainman