

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 14 and 23, T. 1 N., R. 6 W., W.M., Tillamook County, Oregon.

ORIGINAL

Post; now missing, from which a:

10" Hemlock bears S32E 42 lks; now a 16" stub, scribe marks 1/4 exposed.

24" Hemlock bears N41E 33 lks; now only roots remain.

RESTORED CORNER AND BEARING TREES

Set a 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S14 S23 1951 2311", 2 1/2 ft in ground. Raised mound of rock around pipe, from which a:

54" Fir stump bears N55E 12.8 ft; scribed 1/4 S14 2311 BT.

48" Fir stump bears S04W 51.8 ft; 3 RR spikes driven in center of stump.

Placed an Oregon State Board of Forestry metal location poster on 54" fir stump BT and marked it: Sec 14 T1N R6W 1/4 Cor 12.8 ft. S55W.

Dated December 31, 1951.

This corner was restored by Don D. Davis  
Don D. Davis Assistant Forest Engineer  
under my direction.



Present and witnessed by Douglas Stafford Chainman.