

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 21 and 28, T. 1 N., R. 6 W.,  
W. M., Tillamook County, Oregon.

ORIGINAL

Post; now missing, from which a:

- 18" Hemlock bears N35E 4 lks; now 28" snag, marks burnt out.
- 18" Larch bears S30W 19 lks; now 24" Hemlock stub, scribe mark S and part of B exposed.

RESTORED CORNER AND BEARING TREES

Set a 1½" x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY 1/4 S21 S28 1951 2311",  
2½" in ground, from which a:

- 30" Larch stump bears S04E 31.4 ft.; scribed 1/4 S28 BT 2311.
- 28" Larch stump bears N67E 30.0 ft.; scribed 1/4 S21 BT 2311.

Placed an Oregon State Board of Forestry metal location poster  
on 28" Hemlock snag BT and marked it: Sec 21 T1N R6W 1/4  
Cor 2.6 ft. S35W.

Dated December 31, 1951.

This corner was restored by Don D. Davis  
Don D. Davis Assistant Forest Engineer  
under my direction.



Present and witnessed by Douglas Stafford Chairman.