

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 25 and 36 on the East Range Line of T. 1 S., R. 8 W., W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 16"x12"x9"; now broken in three pieces, 5 notches on North face visible, from which a:

- 28" Hemlock bears N76W 90 lks; now missing.
- 12" Hemlock bears N74E 40 lks; now missing.
- 10" Hemlock bears S32E 38 lks; now missing.
- 36" Hemlock bears S35W 59 lks; now missing.

RESTORED CORNER AND BEARING TREES

Set a 1 1/2"x36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY TLS TLS S25 R7W S31 S36 R8W 1952 142", 2 1/2' in ground. Raised mound of stone around pipe, from which a:

- 7' Fir stump bears N2W 91.5'; scribed BT.
- 96" Fir stump bears N84E 48.0'; scribed 1S 7W BT SEC 36.
- 67" Fir stump bears S31W 38.0'; scribed "S31W 38 ft" on top of stump and BT on side of stump.

(The above mentioned BT's were previously scribed by W. Robertson)

27" Fir stump bears S75W 41.9'; scribed TLS R8W S36 BT 142.

Placed an Oregon State Board of Forestry metal location poster on 96" Fir BT and marked it: Sec 31 TLS R7W S25/S36 Cor 48.0' S84W.

Dated January 30, 1952.

This corner was restored by Don D. Davis,
under my direction. Don D. Davis Assistant Forest Engineer



Walter M. Robertson



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman