

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 1 and 12 on the East Range Line of T. 2 S., R. 8 W., W.M., Tillamook County, Oregon.

ORIGINAL

Post; now missing from which a:

- 10" Hemlock bears N52W 24 lks; now missing.
- 14" Fir bears N37E 38 lks; now 29" snag; exposed scribe marks 2S R.
- 5" Maple bears S67E 13 lks; now missing.
- 30" Fir bears S52W 16 lks; now missing.

RESTORED CORNER AND BEARING TREES


Set 1 1/2"x36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S T2S R7W S1 S7 S12 R8W 1952 142", 2 1/2" in ground. Raised mound of stone around pipe, from which a:

- 52" Fir stump bears N24 1/2 W 24.4'; scribed S7 BT.
- 7" Fir stump bears S51W 28.8'; scribed T2S R8W S12 BT 142.
- 60" Fir stump bears N8W 113.3'; scribed T2S R8W S1 BT 142.


Placed an Oregon State Board of Forestry metal location poster on 7" Fir stump BT and marked it: Sec. 12 T2S R8W S1/S12 Cor 28.8' N51E.

Dated January 30, 1952.

This corner was restored by Don D. Davis,
under my direction. Don D. Davis, Assistant Forest Engineer



Walter M. Robertson



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman