

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to T. 1 & 2 S., R. 8 W., W.M., Tillamook County, Oregon.

ON EAST SIDE OF TWP

ORIGINAL

Stone 16"x14"x8"; now 15"x14"x7" with 6 notches on 4 sides, from which a:



- 20" Fir bears N18W 127 lks; now 6' stump N18W 84.8'; with scribe marks BT exposed. Exposed scribe marks T1S.
- 12" Hemlock bears S38E 108 lks; now 5' stub 10' high S38E 73.3'; exposed scribe marks T2S R7W S6.
- 5" Maple bears N40E 52 lks; now missing.
- 6" Alder bears S41W 89 lks; now missing.

RESTORED CORNER AND BEARING TREES


Set 1 1/2"x56" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S T2S R8W R7W S36 S6 S1 T2S 1952 2311" 2 1/2" in ground. Raised mound of stone around pipe, from which a:

- 16" Alder bears N45E 52.3'; scribed T2S R7W S6 BT 2311.
- 5" Alder bears N65W 26.5'; scribed T1S S36 BT.
- 4" Alder bears S48W 73.8'; scribed T2S S1 BT.

Placed an Oregon State Board of Forestry metal location poster on 5" Alder BT and marked it: Sec 36 T1S R8W Twp Cor 26.5' S65E.

Dated January 28, 1952

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman