

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 21, 22, 27, and 28, T. 2 S., R. 7 W.,  
W.M., Tillamook County, Oregon.

ORIGINAL

Post; now missing, from which a:

- 12" Hemlock bears S70E 25 lks; now a 10" stub 4' high;  
scribe marks BT exposed.
- 26" Larch bears S27W 19 lks; now a 26" root stub; exposed  
scribe marks BT.
- 6" Hemlock bears N29W 59 lks; now missing.
- 12" Hemlock bears N71°45'E 93 lks; now missing.

RESTORED CORNER AND BEARING TREES

Set 1½"x36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY T2S R7W S21 S22 S28 S27 1952  
2311", 2½' in ground, from which a:

- 5' Fir stub 20' high bears N53W 38.2'; scribed T2S S21  
BT 2311.
- 30" Fir stub 7' high bears S84E 63.0'; scribed T2S R7W S27  
BT.
- 64" Fir snag bears N18E 45.7'; scribed S22 2311 BT.

Placed an Oregon State Board of Forestry metal location poster  
on 5' Fir stub BT and marked it: Sec 21 T2S R7W Sec Cor 59  
lks S55E.

Pipe is set underneath a 4' Fir log lying NE and SW.

Dated January 29, 1952.

This corner was restored by Don D. Davis  
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris  
Richard A. Morris Compassman