

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 5 & 32, T. 1 & 2 S., R. 7 W.,  
W.M., Tillamook County, Oregon.

ORIGINAL

Post; now missing, from which a:

16" Hemlock bears S52°30'E 29 lks; now 20" stub 9' high;  
scribe marks BT exposed.

18" Hemlock bears N29°30'W 42 lks; now stump badly decayed.

RESTORED CORNER AND BEARING TREES

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY 1/4 S32 S5 1952 2311", 2½"  
in ground, from which a:

69" Fir stump bears S75W 40.2'; scribed 1/4 S5 BT 2311.

8" Alder bears N41°15'E 64.7'; scribed 1/4 S32 BT 2311.

Placed an Oregon State Board of Forestry metal location poster  
on 69" Fir stump BT and marked it: Sec 5 T2S R7W 1/4 Cor  
40.2 Ft. N75E.

Dated February 27, 1952.

This corner was restored by Don D. Davis,  
Don D. Davis Asst. Forest Engineer  
under my direction.



Present and witnessed by Richard A. Morris  
Richard A. Morris Compassman