

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 33 and 34, T. 2 N., R. 7 W.,
W.M., Tillamook County, Oregon.

ORIGINAL

Stone 14" x 8" x 5"; in place marked 1/4, from which a:

- 36" Hemlock bears N20W 34 lks; now root stub.
- 46" Hemlock bears S69°30'E 33 lks; now down stub out of
place, stump hole with part of stub's roots in place.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S33 S34 1952 2311", 2 1/2"
in ground. Raised mound of stone around pipe from which a:

- 6" Fir stump bears S22W 61.5°; scribed 1/4 S33 BT 2311.
- 86" Fir stump bears S31E 74.4°; scribed 1/4 S34 BT.

Placed an Oregon State Board of Forestry metal location poster
on 6" Fir stump BT and marked it: Sec 33 T2N R7W 1/4 Cor
61.5 Ft N22E.

Dated February 26, 1952.

This corner was restored by Don D. Davis
Don D. Davis Asst. Forest Engineer
under my direction.



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman