

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 31 and 32, T. 1 S., R. 7 W.,
W.M., Tillamook County, Oregon.

ORIGINAL

Post; now missing, from which a:

- 16" Hemlock bears S45W 41 lks; now missing.
- 24" Hemlock bears S23E 88 lks; now a 36" stub 25' high;
scribe marks 1 and parts of BT exposed.

RESTORED CORNER AND BEARING TREES


Set $1\frac{1}{8}$ " x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S31 S32 1952 2311", $2\frac{1}{2}$ '
in ground, from which a:

- 4" Fir bears S89°30'E 34.0'; scribed S32.
- 44" Fir stump bears N89W 21.6'; scribed 1/4 S31 BT 2311.

Placed an Oregon State Board of Forestry metal location poster
on original 36" Hemlock BT and marked it: Sec 32 T2S R7W
1/4 Cor 58.1' N23W.

Dated February 28, 1952.

This corner was restored by Don D. Davis,
Don D. Davis Asst. Forest Engineer
under my direction.



Present and witnessed by Richard A. Morris,
Richard A. Morris Compassman