

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 4, 5, 32 and 33, T. 1 & 2 S., R. 7 W.,
W. M., Tillamook County,

ORIGINAL

Post; now missing, from which a:

- 3" Vine maple bears N16E 30 lks; now missing.
- 16" Hemlock bears N23°45'W 60 lks; now 24" stub badly burnt and decayed.
- 6" Alder S69E 8 lks; now 12" stub 4' high, exposed scribe marks W S4.
- 8" Alder bears S59W 38 lks; now 16" stub 5' high badly decayed.

RESTORED CORNER AND BEARING TREES


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R7W S32 S33 S5 S4 T2S 1952 2311", 2½" in ground. Raised mound of stone around pipe, from which a:

- 6' Fir snag bears S80°30'E 136.1'; scribed T2S R7W S4 BT 2311.
- 7' Fir snag bears N27E 121.6'; scribed T1S R7W S33 BT.
- 4" Alder bears S75W 34.8'; scribed S5 BT.
- 4" Maple bears N39°45'W 66.8'; scribed S32 BT.

Placed an Oregon State Board of Forestry metal location poster on 6' Fir snag and marked it: Sec 4 T2S R7W Sec Cor 136.1 Ft. N80°30'W.

Dated February 29, 1952.

This corner was restored by Don D. Davis
Don D. Davis Asst. Forest Engineer
under my direction.



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman