

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 22 and 27, Township 3 North,
Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

14" x 11" x 6" basalt stone, now 14" x 8" x 6" stone marked 1/4,
in place, from which a:

36" Hemlock bears S10E 36 lks; now 36" stump, exposed
scribe marks BT.

4" Fir bears N30°45'E 13 lks, now 38" stump.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S22 S27 1952 2311, 2 1/2" in
ground. Placed 1/4 corner stone on north side of pipe and
raised mound of stone around corner pipe, from which a:

41" Fir stump bears S50°30'E 30.0°; scribed 1/4 S27 BT 2311.

23" Fir stub 18" high bears N56W 6.6°; scribed 1/4 S22 BT.

Placed an Oregon State Board of Forestry metal location poster
on original BT now 36" Hemlock stump and marked it: Sec 27
T3N R5W 1/4 Cor 23.8 ft. N10W.

Dated April 7, 1952.

This corner was restored by Don D. Davis
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by Robert A. Young
Robert A. Young Chairman