

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 23 and 26, Township 3 North,
Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

14" x 10" x 6" basalt stone, now marked 1/4 in place, from which
a:

- 10" Hemlock bears North 23 lks; now missing.
- 36" Hemlock bears S55E 9 lks; now 42" stub badly burnt.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S23 S26 1952 2311, 2 1/2"
in ground. Placed 1/4 stone on north edge of pipe and raised
mound of stone around corner pipe, from which a:

- 15" Noble Fir bears S74W 73.0'; scribed 1/4 S26 BT 2311.
- 8" Hemlock bears N84E 114.1'; scribed 1/4 S23 BT 2311.

Placed an Oregon State Board of Forestry metal location poster
on 9" Alder and marked it: Sec 26 T3N R8W 1/4 Cor 22.8 ft.
N33W.

Dated April 8, 1952.

This corner was restored by Don D. Davis
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by Robert A. Young
Robert A. Young Chairman